




Display Overview



Turning on your display

- Press and hold the **POWER** button to turn your display on.

Turning off your display

- Press and hold the **POWER** button to turn your display off.

Choosing your assist level

- Press the **MENU** button to change your PAS level. The display will scroll through levels in the order of 0 →1→2→3→0.

Enabling and Disabling the throttle

- Use the red button on the right handlebar to enable and disable the bike throttle.
- When the button is pressed in the throttle is enabled.
- If the button is not pressed/outwards the throttle will be disabled.

Operating the headlight and tail light

- Tap the **POWER** button with the display turned on to turn on the headlight and tail light.
- Tap the button again when the lights are turned on to turn them off.
- Turning on the lights will also turn on the display's backlight.

Switch between TRIP meter and ODOMETER

- Hold the **MENU** button to switch the display between ODOMETER and TRIP meter.